



Features:

- **Digital Temperature and Humidity Control:** offers simultaneous regulation of temperature & humidity levels. This ensures optimal conditions for refrigeration units, homes, or other environments.
- **Direct Output:** Provides direct output for easy connection to heating or cooling devices.
- **High Current Capacity:** Capable of handling up to 10A of current, suitable for powering heating or cooling equipment.
- **LED Display:** Features an LED display for clear and easy-to-read temperature and humidity readings.
- **Versatile Application:** Ideal for a wide range of applications, including refrigerators, freezers, incubators, and climate-controlled environments.
- **User-Friendly Interface:** Simple and intuitive interface for easy set-up and operation.
- **Temperature and Humidity Calibration:** Provides calibration options for precise control over temperature and humidity levels.



Specifications:

- Display Type: Digital
- Material: ABS+PCB
- Input voltage: AC110~220V± 10%, DC24V, DC12V
- Measuring temperature range: 0°C~+80°C
- Measuring humidity range: 1%RH~+99%RH
- Accuracy: ±1°, 0.1%RH
- Relay output contact capacity: 10A Direct Output
- Sensor length: 1m
- Item Size: 7.5*5.5*3.1cm / 2.95*2.16*1.22in
- Item Weight: 93g / 3.28oz



Warning: W1099 is Direct Output so when the output terminal is not connected do not power on, to prevent two-stage contact of the wire from sparking.

Instructions:

To set the start-up temperature or humidity: press the "up" button once to display the starting temperature/humidity. Long press the "up" button for about 3 seconds, The required temperature/humidity can be set by the up and down keys.

To set the stop temperature or humidity: Press the "down" button once to display the stop temperature/humidity. Long press the button for about 3 seconds and the stop temperature/humidity number flashes. The required temperature/humidity can be set by the up and down keys

To adjust temperature or humidity: Press "up" and "down" button at the same time.

How to reset the product: Press "down 1" and "down 2" for 3 seconds.

